

Checklist for VES equipment (Offest Wenner)

Station	Terrameter SAS300	<i>In old black nylon bag</i>	
	Short yellow cables with small electrodes for small surveys	<i>Also in nylon bag</i>	
	Charger for Terrameter and its 5-pin cable	<i>Orange box</i>	
Spools	4 x spools of cable with electrode plugs	<i>Small spools, 2 red, 2 blue</i>	
Electrodes	4 x large electrodes	<i>Boxcar-shaped</i>	
Logging form	Printout table to mark readings + clipboard	<i>Pdf in classes folder</i>	
Measuring tools	Trundle (measuring) wheel		
	Tape measures		
Positioning tools	GPS rover emlid receiver		
	GPS base emlid receiver		
	2 x Poles for GPS receivers <i>optional if GPS on ground level</i>		
	Emlid app on smartphone		
	Passwd: emlidreach		
	Save CSV to smartphone!!		
Transporting gear	2-wheeled sack truck	<i>optional</i>	
	Open frame backpack	<i>optional</i>	
	Puncture-proof wheel cart	<i>optional</i>	
First aid kit			
Hi-vis jackets			